

TRUCK OR TRUCK TRACTOR

PREVENTIVE MAINTENANCE REPORT (MD TR §§23-301—23-305; COMAR 11.22; FMCSR §396.17)

Owner's Name: Roy Salmon Trucking LLC

Address: 8333 Pulaski hwy Rosedale MD

Telephone: 443-629-4648

Make: Freightliner Casacada Model: Cascadia

Year: 2015

Company Name: Roy Salmon

Tag Number: 885F99

Manufacturer's Vehicle ID Number: 3AKJGD54FSGB8416

Title Number: _____

COMAR 11.22.02	Components	Passed	Failed	Date Repaired *
.02	Alignment ✓	✓		
.03	Suspension	✓		
.04	Steering	✓		
.05	Brake Systems —	✓		
.06	Brake System — Air	✓		
.07	Tires	✓		
.08	Wheels, Rims, Lock Rings, Studs,	✓		
.09	Accelerator Pedal and Air Throttle	✓		
.10	Fuel Storage and Delivery System	✓		
.11	Exhaust System	✓		
.12	Universal Joints and U-Clamps	✓		
.13	Vehicle Frame, Body, and Sheet	✓		
.14	Lighting	✓		
.15	Electrical System	✓		
.16	Emergency Equipment	✓		
.17	Seats and Seat Belts	✓		
.18	Sun Visor	✓		
.19	Mirrors	✓		
.20	Glazing	✓		
.21	Windshield Wipers and Washers	✓		
.22	Defroster	✓		
.23	Auto Trans Gear Selector / Neutral	✓		

.24	Speedometer and Odometer			
.25	Brake and Clutch Pedal			
.26	Horn			
.27	Hitches and Coupling Devices			
.28	Tanks and Pressure Vessels			

Inspected: (a) Date 11/05/2022

(b) Vehicle Mileage 707083

Inspected By (Print) Carlos Garvante

Repaired By (Print) _____

Certified By (Print) Carlos Garvante

Signature: _____

(Owner or authorized representative)

*** Provide description of repairs and parts used, on reverse side of this form.**